

General Environmental Incident Summary

Incident: 1965 **Date/Time Notice:** 7/2/2013 1130 **DEM Incident No:**

Responsible Party: Westcon Industries

Date Incident: 6/15/2013 **Time Incident:** **Duration:**

County: Morton **Twp:** 139 **Rng:** 81 **Sec:** 22 **Qtr:**

Lat: 46.84312 **Long:** -100.89160 **Method:** Derived from TRS

Location Description: Tesoro Refinery Tanks 718-722 outside of berm at new unloading facility

Submitted By: Patrick Hafner

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person:

735 N. 33rd St.
Bismarck, ND

Distance Nearest Occupied Building:

Type of Incident: Pipeline Leak

Description of Released Contaminant: Diesel Fuel

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Unknown

Risk Evaluation:

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/2/2013

Status: Inspected

Staff: Stockdill, Scott

Updated Volume:

Notes:

Investigated report thoroughly speaking to four members of the Mandan Refinery staff and two members of Westcon Staff to find that Disgruntled Employee reported a false claim in hopes of developing a legal case against Westcon industries.

Site visit on 7/3/2013 showed no spill. No further action necessary.